



**US Army Corps
of Engineers®**

Detroit District
P.O. Box 1027
Detroit, MI 48231-1027
(313) 226-6797
FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L03-59

Date: 25 AUGUST 2003

Waterway: LAKE MICHIGAN

Location: WISCONSIN

CELRE-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL
GREEN BAY HARBOR

1. Condition surveys performed within the Federal navigation channel at Green Bay Harbor, Wisconsin during May - August 2003, indicate shoaling as shown on the following sheets.
2. Mariners are urged to use extreme caution in the area.
3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L03-59. Internet address: <http://www.lre.usace.army.mil> Go to: Detroit Home Page, Who We Are, Operations Home Page.

THOMAS H. MAGNESS
Lieutenant Colonel, U.S. Army
District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2003.



Shoals indicate least available depth below I.G.L.D.

All soundings are in feet and are referred to Low Water Datum 576.8 ft. above Mean Water Level at Father Point, Quebec, IGLD, 1955.

The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.

Surveys taken: MAY, JUNE 2003




GREEN BAY HARBOR, WISCONSIN

CONDITION OF CHANNEL

ISSUED: 25 AUGUST 2003

U.S. Army Engineer District, Detroit

All soundings are in feet and are referred to Low Water Datum 576.8 ft. above Mean Water Level at Father Point, Quebec, IGLD, 1955.



The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.



Shoals indicate least available depth below I.G.L.D.


Surveys taken: JUNE 2003

GREEN BAY HARBOR, WISCONSIN

CONDITION OF CHANNEL

ISSUED: 25 AUGUST 2003

U.S. Army Engineer District, Detroit



All soundings are in feet and are referred to Low Water Datum 576.8 ft. above Low Water Datum at Father Point, Quebec, IGLD, 1955.

The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.



Shoals indicate least available depth below I.G.L.D.

Surveys taken: JUNE 2003

GREEN BAY HARBOR, WISCONSIN

CONDITION OF CHANNEL


ISSUED: 25 AUGUST 2003

U.S. Army Engineer District, Detroit

The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.

Surveys taken: JUNE 2003

Soundings are in feet and are referred to Low Water Datum 576.8 ft. above Mean Water Level at Father Point, Quebec, IGLD, 1955.




GREEN BAY HARBOR, WISCONSIN

CONDITION OF CHANNEL

ISSUED: 25 AUGUST 2003

U.S. Army Engineer District, Detroit

All soundings are in feet and are referred to Low Water Datum 576.8 ft. above Mean Water Level at Father Point, Quebec, IGLD, 1955.



PROJECT DEPTH: 24 FT.

AREA 6

The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.



Shoals indicate least available depth below I.G.L.D.


Surveys taken: JUNE, AUGUST 2003

GREEN BAY HARBOR, WISCONSIN

CONDITION OF CHANNEL

ISSUED: 25 AUGUST 2003

U.S. Army Engineer District, Detroit



All soundings are in feet and are referred to Low Water Datum 576.8 ft. above Mean Water Level at Father Point, Quebec, IGLD, 1955.

The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.



Shoals indicate least available depth below I.G.L.D.

Surveys taken: AUGUST 2003

GREEN BAY HARBOR, WISCONSIN

CONDITION OF CHANNEL

ISSUED: 25 AUGUST 2003

U.S. Army Engineer District, Detroit